

PORT OF BOSTON

EST 1884

Port of Boston Ltd, Boston
Lincolnshire PE21 6BN

Tel: 01205 365571 Fax: 01205 310126

<http://www.victoriagroup.co.uk>

Dated: 18.04.19

NOTICE TO MARINERS 020/2019

Barrier Bypass Channel – Scour Matting

Mariners are advised that the obstructing scour mat within the Barrier Bypass Channel has now been removed.

The bypass channel depth is now approximately 1.8M (-1.9M AOD) above Boston Dock Sill.

This notice supersedes Notice to Mariners 014/2019.

Harbour Master
Port of Boston Ltd