

Port of Boston Ltd, Boston Lincolnshire PE21 6BN

Tel: 01205 365571 Fax: 01205 310126

http://www.victoriagroup.co.uk Dated: 25.09.18

NOTICE TO MARINERS 055/2018

Bypass Channel Tidal Flow

Mariners are advised that the Flood Barrier cofferdam is nearing completion. As a result of this, the river will only be able to flow through the 18m wide temporary bypass channel.

This will cause an increase in tidal flow speeds with localized changes to the direction of flow.

Mariners are advised to proceed with caution when navigating through the bypass channel and adjacent areas.

The Guard Vessel remains on station and can be contacted on VHF Channel 12 for advice and assistance.

Harbour Master
Port of Boston Ltd