

PORT OF BOSTON

EST 1884

Port of Boston Ltd, Boston
Lincolnshire PE21 6BN

Tel: 01205 365571 Fax: 01205 310126

<http://www.victoriagroup.co.uk>

Dated: 09.03.19

NOTICE TO MARINERS 014/2019

Barrier Bypass Channel – Scour Matting

Mariners are advised that there appears to be a number of scour mats within the Barrier Bypass Channel which are giving a clearance under keel of less than anticipated.

The mats causing a problem are estimated to be approximately 1.8M (-1.9M AOD) above Boston Dock Sill when clearance should be 0.7M (-3.0 AOD).

The contractors will remove the scour matting causing the problem as soon as practicable. Attached photo shows the approximate location within the bypass channel of the problem area.

Harbour Master
Port of Boston Ltd

