

Port of Boston Ltd, Boston Lincolnshire PE21 6BN

Tel: 01205 365571 Fax: 01205 310126

http://www.victoriagroup.co.uk

Dated: 5.03.20

NOTICE TO MARINERS 015/2020

Shallow Buried Cables / Isolated Danger Mark

Mariners are advised that an Isolated Danger Buoy FI(2)10s has been placed in position 53 01.529N, 000 25.661E. This buoy indicates shallow buried cables.

Harbour Master
Port of Boston Ltd