

PORT OF BOSTON

EST 1884

Port of Boston Ltd, Boston
Lincolnshire PE21 6BN

Tel: 01205 365571 Fax: 01205 310126

<http://www.victoriagroup.co.uk>

Dated: 01.12.19

NOTICE TO MARINERS 063/2019

Barrier – Bypass Channel

Mariners are advised and reminded that the most recent survey shows water depths in the bypass channel are 1.2M above dock sill.

Due to the hard nature of scour protection matting care should be taken when navigating through the bypass channel.

Harbour Master
Port of Boston Ltd