

Port of Boston Ltd, Boston Lincolnshire PE21 6BN

Tel: 01205 365571 Fax: 01205 310126

http://www.victoriagroup.co.uk

Dated: 06/09/2021

NOTICE TO MARINERS 51/2021

Removal of Aids to Navigation (Lights)

Mariners are advised that following the closure of the Boston Barrier By-Pass Channel, the temporary Aids to Navigation in the positions below marking the by-pass channel have been permanently removed.

- N19408 "Boston Barrier Bypass (Temp)" lighted beacon in position Lat. 052° 57.990' N Long. 000° 01.410' W
- N19409 "Boston Barrier Bypass (Temp)" lighted beacon in position Lat. 052° 57.990' N Long. 000° 01.410' W
- N19410 "Boston Barrier Bypass (Temp)" lighted beacon in position Lat. 052° 57.990' N Long. 000° 01.410' W
- N19411 "Boston Barrier Bypass (Temp)" lighted beacon in position Lat. 052° 57.990' N Long. 000° 01.410' W

Harbour Master Port of Boston Ltd